

BUC/13/2 footpath Buckingham Lace Hill


There are 3 issues with the footpath BUC/13/2

Item 1 there is still no designated pathway from at A421 and Needlepin Way marked in red in Map 1.

Item 2 although good work has been done on the section running alongside the A421 so that pedestrians are not now required to walk along the edge of the A421 there are a group of large trees indicated with the green dot that would make it very difficult to navigate with a small push chair.

Item 3 there is no sign post at the location marked on Map 1 in purple indicating that the definitive path crosses the A421 to BUC/13/3. In fact it appears the small path indicator has been tampered with.

Map 1



Item 1

Effectively BUC/13/2 effectively is a dead ends until a pathway is marked out to Needlepin way



Item 2

Group of 4 trees in close proximity to each other making is suitable for foot traffic only. At least one tree needs to be removed to ground level. Which would also give the other trees space to grow.



Item 3

The small path arrow has been re-set to point along the A421 when the path in fact crosses the A421 at this point to join BUC/13/3



Public foot path sign on the north side of the A421

